



Figure 1 – Shackle attached to lifting eye before pre-use inspection



Figure 2 – Damaged shackle



Figure 3. Damaged lifting eye